

## 1100 ALVIRA ST.

1100 S. Alvira Street APN: 5087014001 Contributor 1933

Builder: Paul Harter Original owner: Paul Harter

A one-story single-family residence in the Spanish Colonial Revival style. It has an irregular plan and its cladding is smooth stucco and brick. Details include applied decoration, arch(es), decorative wood elements, a tower volume, and a wing wall. The roof is crossed gable, hipped, and flat with bargeboards, clay tile coping, corbels, a cornice, eave returns, exposed purlins, a flat parapet, a tower, a turret, and a weathervane, surfaced with clay tile and a material not visible. Related features include a detached garage and a walled entry courtyard. Alterations: appears to be unaltered.

1101 S. Alvira Street APN: 5087011014 Contributor 1933

Builder: Theo M. Johnson Original owner: Theo M. Johnson

A one-story single-family residence in the Spanish Colonial Revival style. It has an irregular plan and its cladding is smooth stucco. Details include decorative wood elements, arch(es), a wing wall, and grilles. The roof is side gable and front gable with clay tile coping, bargeboards, open eaves, exposed purlins, and exposed rafter tails, surfaced with clay tile. Related features include a detached garage. Alterations: appears to be unaltered.

1108 S. Alvira Street APN: 5087014002 Contributor 1934

Original owner: Albert Rothenberg

A two-story single-family residence in the Spanish Colonial Revival style. It has an irregular plan and its cladding is smooth stucco. Details include applied decoration, arch(es), balconettes, corbels, decorative wood elements, grilles, pierced screen(s), a string course, and a wing wall. The roof is side gable with clay tile coping, exposed rafter tails, and a turret, surfaced with clay tile. Related features include a porte cochere. Alterations: appears to be unaltered.

1111 S. Alvira Street APN: 5087011013 Contributor 1934

Builder: P.K. McKissock Original owner: P.K. McKissock

A one-story single-family residence in the Spanish Colonial Revival style. It has an irregular plan and its cladding is smooth stucco. Details include arch(es), a wing wall, and a tower volume. The roof is front gable, side gable, and hipped with clay tile coping, bargeboards, molded eaves, a turret, a weathervane, open eaves, exposed purlins, exposed rafter tails, and a tower, surfaced with clay tile. Related features include a porte cochere and a gate. Alterations: appears to be unaltered.

1112 S. Alvira Street APN: 5087014003 Contributor 1934

Original owner: Albert Rothenberg

A one-story single-family residence in the Spanish Colonial Revival style. It has an irregular plan and its cladding is textured stucco. Details include applied decoration, arch(es), decorative tile, decorative wood elements, and a wing wall. The roof is front gable, hipped, flat, and shed with bargeboards, clay tile coping, exposed purlins, exposed rafter tails, a flat parapet, and molded eaves, surfaced with clay tile and a material not visible. Related features include a detached garage and a porte cochere. Alterations: decorative tile added, restuccoed (incompatible), security window bars added, and walkway altered.

1115 S. Alvira Street APN: 5087011012 Contributor 1934

Builder: W.H. Coulter Original owner: W.H. Coulter

A one-story single-family residence in the Spanish Colonial Revival style. It has an irregular plan and its cladding is smooth stucco. Details include arch(es), grilles, a wing wall, a tower volume, and pierced screen(s). The roof is front gable, hipped, and flat with bargeboards, clay tile coping, molded eaves, open eaves, exposed purlins, exposed rafter tails, and a weathervane, surfaced with clay tile and a material not visible. Related features include a porte cochere, a gate, and a detached garage. Alterations: appears to be unaltered.

1116 S. Alvira Street APN: 5087014004 Contributor 1934

Original owner: W.H. Mandler

A one-story single-family residence in the Spanish Colonial Revival style. It has an irregular plan and its cladding is smooth stucco. Details include applied decoration, arch(es), grilles, pierced screen(s), a tower volume, and a wing wall. The roof is front gable, flat, shed, and conical with clay tile coping, a flat parapet, open eaves, and a tower, surfaced with clay tile and a material not visible. Related features include ancillary building(s), a porte cochere, and a walled entry courtyard. Alterations: garage altered/replaced, gate added/replaced, primary door replaced, and security door added.

1119 S. Alvira Street APN: 5087011011 Contributor 1934

Architect: L.B. Boran Builder: L.B. Boran Original owner: L.B. Boran

A one-story single-family residence in the Spanish Colonial Revival style. It has an irregular plan and its cladding is smooth stucco. Details include arch(es), a wing wall, a tower volume, and pierced screen(s). The roof is side gable, hipped, and front gable with clay tile coping, molded eaves, and exposed rafter tails, surfaced with clay tile. Related features include a porte cochere, a detached garage, and a gate. Alterations: light fixture added/replaced, walkway altered, and driveway altered.

1123 S. Alvira Street APN: 5087011010 Contributor 1934

Builder: M. Burgbacher & Sons Original owner: J.J. Schwartz

A one-story single-family residence in the Spanish Colonial Revival style. It has an irregular plan and its cladding is smooth stucco and wood shiplap. Details include decorative wood elements, a tower volume, and decorative tile. The roof is side gable, front gable, and hipped with bargeboards, molded eaves, open eaves, exposed rafter tails, and exposed purlins, surfaced with clay tile. Related features include a gate and a porte cochere. Alterations: gate added/replaced and light fixture added/replaced.

1124 S. Alvira Street APN: 5087014005 Contributor 1934

Original owner: S.M. Soll

A one-story single-family residence in the Spanish Colonial Revival style. It has an irregular plan and its cladding is textured stucco and cut stone. Details include applied decoration, arch(es), and a tower volume. The roof is front gable, hipped, flat, and shed with clay tile coping, decorative vents, a flat parapet, molded eaves, a tower, and a turret, surfaced with clay tile and a material not visible. Related features include a detached garage, a porte cochere, and a walled entry courtyard. Alterations: awnings added, gate added/replaced, restuccoed (compatible), and security window bars added.

1127 S. Alvira Street APN: 5087011009 Contributor 1934

Builder: J.N. Rosenthal Original owner: Publix Construction & Investment Co. Ltd.

A one-story single-family residence in the Spanish Colonial Revival style. It has an irregular plan and its cladding is smooth stucco and brick. Details include arch(es), a tower volume, and a wing wall. The roof is front gable, side gable, and hipped with clay tile coping, molded eaves, a tower, and a turret, surfaced with clay tile. Related features include a detached garage, a gate, and a porte cochere. Alterations: light fixture added/replaced.

1130 S. Alvira Street APN: 5087014006 Contributor 1934

Builder: Haun & Renton Original owner: Mary Rampon Photo 11

A one-story single-family residence in the Spanish Colonial Revival style. It has an irregular plan and its cladding is smooth stucco and brick. Details include applied decoration, arch(es), decorative wood elements, grilles, a tower volume, and a wing wall. The roof is side gable, hipped, flat, and shed with bargeboards, clay tile coping, decorative vents, exposed purlins, exposed rafter tails, a flat parapet, molded eaves, a tower, and a turret, surfaced with clay tile and a material not visible. Related features include a detached garage and a porte cochere. Alterations: no major alterations, grilles added/replaced, and light fixture added/replaced.

1132 S. Alvira Street APN: 5087014007 Contributor 1935

Builder: Clint Harter Original owner: Clint Harter

A one-story single-family residence in the Spanish Colonial Revival style. It has an irregular plan and its cladding is smooth stucco and brick. Details include applied decoration, arch(es), corbels, decorative tile, and a tower volume. The roof is crossed gable, hipped, flat, and shed with bargeboards, clay tile coping, a cornice, exposed rafter tails, a flat parapet, molded eaves, a tower, and a turret, surfaced with clay tile and a material not visible. Related features include a walled entry courtyard. Alterations: no major alterations, awnings added, decorative tile added, and security window bars added.

1133 S. Alvira Street APN: 5087011008 Contributor 1934

Builder: J.N. Rosenthal Original owner: Publix Construction & Investment Co. Ltd.

A one-story single-family residence in the Spanish Colonial Revival style. It has an irregular plan and its cladding is smooth stucco. Details include arch(es), pierced screen(s), and a tower volume. The roof is front gable and hipped with bargeboards, molded eaves, open eaves, exposed purlins, exposed rafter tails, a turret, and a tower, surfaced with clay tile. Related features include a detached garage, a porte cochere, and a gate. Alterations: some windows replaced and light fixture added/replaced.

1136 S. Alvira Street APN: 5087014008 Contributor 1935

Builder: P. Van Wagner Original owner: Abe Weisenberg

A one-story single-family residence in the Spanish Colonial Revival style. It has an irregular plan and its cladding is textured stucco. Details include applied decoration, arch(es), and a tower volume. The roof is crossed gable, hipped, flat, and shed with clay tile coping, decorative vents, exposed rafter tails, a flat parapet, and a tower, surfaced with clay tile and a material not visible. Related features include a detached garage and a walled entry courtyard. Alterations: gate added/replaced, restuccoed (incompatible), security door added, and some windows replaced.

1139 S. Alvira Street APN: 5087011007 Contributor 1933

Builder: Ley Bros. Original owner: Anna L. Heath

A one-story single-family residence in the Minimal Traditional style. It has an irregular plan and its cladding is smooth stucco. The roof is front gable and hipped with a dove-cote, surfaced with composition shingle. Related features include a carport and a gate. Alterations: entry wall or fence added and walkway altered.

1143 S. Alvira Street APN: 5087011006 Contributor 1934

Builder: Ley Bros. Original owner: Anna L. Heath

A one-story single-family residence in the Spanish Colonial Revival style. It has an irregular plan and its cladding is smooth stucco. Details include arch(es) and grilles. The roof is front gable and side gable with clay tile coping and molded eaves, surfaced with clay tile. Related features include a porte cochere and a gate. Alterations: appears to be unaltered.

1144 S. Alvira Street APN: 5087014009 Contributor 1933

Builder: M. Burgbacher & Sons Original owner: J.B. Miller

A one-story single-family residence in the Spanish Colonial Revival style. It has an L-shaped plan and its cladding is textured stucco, brick, and beadboard. Details include applied decoration and decorative wood elements. The roof is crossed gable and flat with clay tile coping, decorative vents, exposed rafter tails, a flat parapet, and scalloped wood detail at front gable, surfaced with clay tile and a material not visible. Related features include a detached garage, a gate, and a walled entry courtyard. Alterations: entry wall or fence added, gate added/replaced, and security window bars added.

1146 S. Alvira Street APN: 5087014010 Contributor 1934

Builder: George P. Foote Original owner: Mrs. Mr. P.B. Swartzel

A one-story single-family residence in the Spanish Colonial Revival style. It has an irregular plan and its cladding is textured stucco. Details include applied decoration, arch(es), grilles, a tower volume, and a wing wall. The roof is crossed gable, hipped, and flat with clay tile coping, a flat parapet, molded eaves, a tower, and a turret, surfaced with clay tile and a material not visible. Related features include a porte cochere and a walled entry courtyard. Alterations: awnings added, gate added/replaced, grilles added/replaced, restuccoed (compatible), and walkway altered.

1149 S. Alvira Street APN: 5087011005 Contributor 1933

Original owner: Samuel Fischer

A one-story single-family residence in the Storybook style. It has an irregular plan and its cladding is smooth stucco. Details include arch(es), a wing wall, and grilles. The roof is front gable, side gable, hipped, and flat with clay tile coping, molded eaves, a flat parapet, a tower, and a turret, surfaced with clay tile and a material not visible. Related features include a detached garage and a gate. Alterations: gate added/replaced and grilles added/replaced.

1154 S. Alvira Street APN: 5087014011 Contributor 1933

Builder: M. Burgbacher & Sons Original owner: D.W.H. Stringham

A one-story single-family residence in the Spanish Colonial Revival style. It has an irregular plan and its cladding is smooth stucco and brick. Details include applied decoration, decorative wood elements, and a wing wall. The roof is side gable, flat, and shed with clay tile coping, decorative vents, exposed rafter tails, a flat parapet, and a turret, surfaced with clay tile and a material not visible. Related features include a detached garage and a porte cochere. Alterations: appears to be unaltered.

1155 S. Alvira Street APN: 5087011004 Contributor 1934

Original owner: Samuel Fischer

A one-story single-family residence in the Spanish Colonial Revival style. It has an irregular plan and its cladding is smooth stucco. Details include arch(es), a wing wall, and a tower volume. The roof is front gable, side gable, and flat with molded eaves, clay tile coping, decorative vents, exposed purlins, exposed rafter tails, open eaves, a tower, and a turret, surfaced with clay tile and a material not visible. Related features include a gate. Alterations: visible solar panels and walkway altered.

1159 S. Alvira Street APN: 5087011003 Contributor 1934

Original owner: Samuel Fischer

A one-story single-family residence in the Spanish Colonial Revival style. It has an irregular plan and its cladding is smooth stucco. Details include arch(es) and a wing wall. The roof is front gable, side gable, and hipped with bargeboards, a tower, open eaves, exposed rafter tails, exposed purlins, and decorative vents, surfaced with clay tile. Related features include a gate and a porte cochere. Alterations: gate added/replaced and railings added/replaced.

1160 S. Alvira Street APN: 5087014012 Contributor 1934

Builder: George P. Foote Original owner: George P. Foote

A one-story single-family residence in the Minimal Traditional style. It has an L-shaped plan and its cladding is smooth stucco, brick, and wood shiplap. Details include applied decoration and decorative wood elements. The roof is crossed gable with decorative vents, exposed rafter tails, vent roof dormers, and scalloped wood detail at front gable, surfaced with composition shingle. Alterations: appears to be unaltered.

1161 S. Alvira Street APN: 5087011002 Contributor 1935

Builder: M. Burgbacher & Sons Original owner: Dr. Arthur M. Campbell

A one-story single-family residence in the Spanish Colonial Revival style. It has an irregular plan and its cladding is smooth stucco. Details include decorative wood elements. The roof is hipped, side gable, and front gable with clay tile coping, bargeboards, exposed purlins, exposed rafter tails, open eaves, a turret, and a tower, surfaced with clay tile. Related features include a gate, a porte cochere, and a fountain. Alterations: gate added/replaced.

1164 S. Alvira Street APN: 5087014013 Contributor 1934

Builder: J.E. Lloyd-Jones Original owner: L.F. Lounsberry

A one-story single-family residence in the Spanish Colonial Revival style. It has an irregular plan and its cladding is textured stucco. Details include applied decoration. The roof is crossed gable and flat with clay tile coping, decorative vents, exposed rafter tails, and a flat parapet, surfaced with clay tile and a material not visible. Related features include a detached garage and a porte cochere. Alterations: no major alterations, gate added/replaced, and security window bars added.

1167 S. Alvira Street APN: 5087011001 Contributor 1937

Builder: Spiros George Ponty Original owner: Sam B. & Anna Ray Hyman

A one-story single-family residence in the Spanish Colonial Revival style. It has an irregular plan and its cladding is smooth stucco. Details include arch(es) and a wing wall. The roof is side gable and hipped with clay tile coping, decorative vents, and molded eaves, surfaced with clay tile. Related features include a detached garage. Alterations: gate added/replaced and walkway altered.

1170 S. Alvira Street APN: 5087014014 Contributor 1934

Builder: J.E. Lloyd-Jones Original owner: Mr. Nick Svalas

A one-story single-family residence in the Minimal Traditional style. It has an irregular plan and its cladding is wood clapboard. Details include applied decoration and decorative wood elements. The roof is crossed gable with open eaves and vents, surfaced with composition shingle. Related features include a detached garage. Alterations: garage door replaced, primary door replaced, and pergola-like canopy added to primary en